

NEW

SHIMMY DAMPENER

for Cessna 150, 152, 172, 175 and 182 aircraft

FAA-PMA APPROVED



Part Number: MC0442512-1 Replaces 0442512-1 and 0542119-1

Improved design for consistent dampening action!

- Oversize shaft for rigid strength
- Wear resistant hard anodized housing
- Better shimmy dampening
- Totally repairable
- Self lubricating
- Costs less than the throw away rubber dampener

Temperature compensated hydraulics

- Almost no service required
- Even the first minor movements are dampened
- Consistent dampening action
- No oil leaks

Available at amazon.com