



Note : After examining several original sets of Navajo/Chieftain Interior double window plastics, it has been found that of lip and window opening is not consistent. Trimming and possible light reheat of lip area may be necessary. The K55258-08, K55254-03 are sold with the buyer being fully aware of these conditions.

Windows and Upper Cabin




PA-31-300,310

Windows and Upper Cabin




PA-31-300,310

Windows and Upper Cabin




PA-31-300,325

Windows and Upper Cabin




PA-31-300,325

Windows and Upper Cabin



PA-31-300,325


Lower Cabin



PA-31-300,325


Note : After examining several original sets of Navajo/Chieftain Interior double window plastics, it has been found that of lip and window opening is not consistent. Trimming and possible light reheat of lip area may be necessary. The K55258-08, K55254-03 are sold with the buyer being fully aware of these conditions.

Windows and Upper Cabin




PA-31-300,325

Windows and Upper Cabin




PA-31-350

Windows and Upper Cabin




PA-31-350

Lower Cabin




PA-31-350


Windows and Upper Cabin




PA-31-350




PA-31-350




PA-31-300.310.325.350




PA-31-300.310.325.350




PA-31-300.310.325.350



PA-31-300.310.325.350



PA-31-300.310.325.350



PA-31T