

**NEW**

# SHIMMY DAMPENER

for Cessna 150, 152, 172, 175 and 182 aircraft

FAA-PMA APPROVED



**Part Number:** MC0442512-1 Replaces 0442512-1 and 0542119-1

**Improved design for consistent dampening action!**

- Oversize shaft for rigid strength
- Wear resistant hard anodized housing
- Better shimmy dampening
- Totally repairable
- Self lubricating
- Costs less than the throw away rubber dampener

**Temperature compensated hydraulics**

- Almost no service required
- Even the first minor movements are dampened
- Consistent dampening action
- No oil leaks